

## **KB8113 Firmware V2.2.51\_230109 Release Note** (2023-01-19)

Device Model	DS-KB8113-IME1
Firmware Version	V2.2.51_230109
iVMS-4200 Version	Latest version
Hik-Connect APP	Latest version

### Reason of Upgrade

Add new feature, fix bugs, enhance products quality and meet customers' requirements.

### **New Feature**

1. When adding KB8113 to Hik-Connect directly, it supports capture and uploading picture to hik-connect when the call button is pressed (there was no picture before).

### **Modified Feature**

- 1. Optimize exit button detection logic and increase button detection sensitivity
- 2. Correction of the audio file in standard Portuguese


# **KB8113 Firmware V2.2.51\_220713 Release Note** (2022-08-02)

Device Model	DS-KB8113-IME1
Firmware Version	V2.2.51_220713
iVMS-4200 Version	Latest version
Hik-Connect APP	Latest version

#### **Fix**

1. Supports CS registration mode in SIP registration, support clients initiate registration just once to the server to finish the registration





- 2. Supports multi-language switching without device rebooting.
- 3. Fixed the problem that the actual lock time is more than the set duration of 1 second.

# **KB8113 Firmware V2.2.51\_220507 Release Note** (2022-05-30)

Device Model	DS-KB8113-IME1
Firmware Version	V2.2.51_220507
iVMS-4200 Version	Latest version
Hik-Connect APP	Latest version

#### **FIX**

- 1. Compatible with the new version Indoor Stations:
  - DS-KH9310-WTE1(B)
  - ➤ DS-KH9510-WTE1(B)
  - ➤ DS-KH6350-WTE1
  - ➤ DS-KH6350-TE1
  - ➤ DS-KH6320-LE1(B)
  - ➤ DS-KH6320-LE1(B)/White
  - DS-KH6320-TE1(B)
  - DS-KH6320-WTE1(B)
  - ➤ DS-KH6360-TE1



- 2. Compatible with more card reader models:
  - ➤ DS-K1108AD
- 3. Fix the problem that standard SIP cannot be automatically registered after restarting.
- 4. Compatible with the latest version of Google Chrome for remote upgrade.

# **KB8113 Firmware V2.2.51\_211110 Release Note** (2021-11-22)

Device Model	DS-KB8113-IME1
Firmware Version	V2.2.51_211110
iVMS-4200 Version	Latest version
Hik-Connect APP	Latest version

#### **FIX**

1. Fixed some bugs.

## KB8113 Firmware V2.2.51\_210908 Release Note (2021-09-08)

Device Model	DS-KB8113-IME1
Firmware Version	V2.2.51_210908
iVMS-4200 Version	Latest version
Hik-Connect APP	4.13.1 or above

#### FIX

1. Solve the problem of calling Hik-connect failure after enabling Hik-connect for the first time.


# KB8113 Firmware V2.2.51\_210816 Release Note (2021-08-16)

Device Model	DS-KB8113-IME1
Firmware Version	V2.2.51_210816
iVMS-4200 Version	Latest version
Hik-Connect APP	4.13.1 or above



#### **Modify**

1. HiK-Connect is disabled and Verification code is empty by default.



# KB8113 Firmware V2.2.51\_210630 Release Note (2021-07-12)


Device Model	DS-KB8113-IME1
Firmware Version	V2.2.51_210630
iVMS-4200 Version	Latest version
Hik-Connect APP	4.13.1 or above

### **Modify**


1. Since V2.2.51\_210630, remote degradation of devices is not supported in all subsequent versions. When degradation occurs, it will prompt Upgrading failed.




Notice: Although the device can be degraded by serial port, the device will fail to start and cannot change the version by using serial port again, which means that the device will be completely unusable.



- 2. Newly support for French voice prompt "calling", "the line is busy" and "the door is open"
- 3. The method of adding sub door station is changed to the same method as protocol 1.0. (Fill in the Main Door Station IP and Registration Password in the configuration interface of Sub Door Station)








Note: you can refer to the attached file below about how to add a Sub door station.



How to add a single sub door st

4. Hik-Connect function is disabled by default.



## KB8113 Firmware V2.2.46\_210430 Release Note (2021-04-30)

Device Model	DS-KB8113-IME1
Firmware Version	V2.2.46_210430
iVMS-4200 Version	Latest version
Hik-Connect APP	4.13.1 or above


#### **NOTE**

Registration password will correspond to the serial number to prevent other devices from invading the system


#### **New Function**



1. The changed name of the door station will be displayed on the call interface or preview interface of the indoor station




2. Add indoor station or sub-door station to iVMS-4200 or WEB to add default value




3. If the Registration Password in the door station WEB interface has been configured, it will be displayed in cipher text



4. Video Intercom Server IP (Private SIP server IP) naming changed to Center IP




5. The WEB or iVMS-4200 interface community number, building number, and unit number of the door station will be stored in the advanced settings column instead of being displayed directly



6. Support doorphone mode, when this function is enabled, the door station will no longer actively synchronize the information of the indoor station






#### Modify

1. Now the doorbell KB8113 has an intercom button on the WEB interface, which can actively send intercom



2. Change the Regist Password to the Registration Password in the export excel



### **Customer Impact and Recommended Action**

This update refers to function/compatibility improvement and will take effect automatically after the Date of Change. We are very sorry for any inconvenience of use-habit changes caused by this action.

### Note:

- Hikvision reserves the right to change, alter or withdraw the above notification without prior notice.
- Product design and specifications are subject to change without prior notice.

For any questions and request for this firmware, please contact our local technical support team.

- The Hikvision firmware may contain errors known as errata, which may cause the product



Hikvision Digital Technology CO., Ltd. No. 555 Qianmo Road, Binjiang District, Hangzhou 310051, China

Tel: +86-571-8807-5998 FAX: +86-571-8993-5635

Email: overseabusiness@hikvision.com