

Network Video Recorder

Version: V4.85.040_260725

Release Note

Firmware Basic Information	Firmware Version:	V4.85.040_build260725
	SDK Version:	NA
	Play Library:	7.4.2.62
	Web component:	V5.1.45_R0102 build 260721
	OpenSDK Version:	V2.16.14

Reason of Upgrade

New features and problem fixes

New Features

N/A

Modified functions

1. Fixed the issue where the Hik-Connect replay only showed a portion of the footage from that day.
2. Fix the issue where the device does not prompt "Please manually turn off the power" when shutting down, but instead restarts directly.
3. Fix the issue of HTTP alarm monitoring and push alarm loss.
4. Fix the issue of truncation of platform channel names in ONVIF.
5. Fix no longer default to turning on sound and light camera light alarm.
6. Fix the device to enable OTAP or Hik-Connect, causing it to crash after restarting.

Customer Impact and Recommended Action

This new firmware upgrade is to improve product performance, and will take effect automatically after upgrading from previous versions. We'd like to inform you the above changes. Also, we are sorry for any possible inconvenience of use-habit changes caused by this action.

For questions or concerns, please contact our local technical support.

Note:

- Hikvision has all rights to alter, modify and cancel this notice.
- Hikvision doesn't give any guarantee for old models' stock.
- Hikvision is not liable for any typing or printing errors.
- For special model's change details, please contact our local technical support team.