

Network Video Recorder

Version: V4.84.030 build 250624

Release Note

	Firmware Version:	V4.84.030 build 250624	
Firmware Basic Information	SDK Version:	NA	
	Play Library:	4.0.2409.1	
	Web component:	V5.0.27_R0102 build 250609	
	OpenSDK Version:	V2.16.3	

Reason of Upgrade

New features and known problem fixes

New Features

1. Add 2 1080P decoding capabilities

Modified functions

- 1. Remove attribute filtering function
- 2. Fixed the DDNS connection issue
- 3. Fixed the issue where selecting vehicles, frames, or lines for retrieval on the local playback page resulted in the inability to retrieve vehicle targets (actual vehicle targets exist) during page inspection
- 4. Fixed the issue where the "Enable" character in the header would shift to the right when the image search configuration interface was enabled to be turned off
- 5. Fixed the issue on the Hik-Connect platform where devices frequently drag playback and resources are not released in a timely manner, resulting in playback exceeding the limit
- 6. Modify the number of intercom channels for devices that only support HDMI/VGA from the same source and do not support heterogeneous switching to only support one channel
- 7. Fix bug where decoding ability cannot be restored after disabling Acusearch
- 8. After disabling Acusearch, the engine switches to advanced motion detection mode, a new channel is connected, and advanced motion detection is not enabled by default



<u>Customer Impact and Recommended Action</u>

This new firmware upgrade is to improve product performance, and will take effect automatically after upgrading from previous versions. We'd like to inform you the above changes. Also, we are sorry for any possible inconvenience of use-habit changes caused by this action.

For questions or concerns, please contact our local technical support.

Note:

- Hikvision has all rights to alter, modify and cancel this notice.
- Hikvision doesn't give any guarantee for old models' stock.
- Hikvision is not liable for any typing or printing errors.
- For special model's change details, please contact our local technical support team.