

Mobile Video Recorder V5.3.1 Release Note

Firmware Basic Information	Firmware Version:
	Encoding Version:
	Web Version:

Reason of Upgrade

Add new features and optimize product performance.

New features

None

Modified functions

1. Fix the problem that 56 and 76 series MVR WIFI58 cannot be used;
2. Fix the VGA failure problem of 7608HN;

Related product list

MVR	DS-MP5604,DS-MP5604-SD:
	MP5604_EN_GM_5.3.1_211229.zip
	DS-MP5604N
	MP5604_EN_GM_5.3.1_210923.zip
	DS-MP7608
	MP7608_EN_GM_5.3.1_211229.zip
	DS-MP7608H
	MP7608H_EN_GM_5.3.1_210923
	DS-MP7608HN
	MP7608HN_EN_GM_5.3.1_220117.zip
	DS-MP7608HN(B)
	MP7608HN_B_EN_GM_5.3.1_211122

Customer Impact and Recommended Action

This new firmware upgrade is to improve product performance, and will take effect automatically after upgrading from previous versions. We'd like to inform you the above changes. Also, we are sorry for any possible inconvenience of use-habit changes caused by this action.

Note:

- Hikvision has all rights to alter, modify and cancel this notice.
- Hikvision doesn't give any guarantee for old models' stock.
- Hikvision is not liable for any typing or printing errors.
- For special model's change details, please contact our local technical support team.