Network Camera Firmware Version: V5.8.61 SP

Release Note

Firmware Basic Information	Firmware Version:	V5.8.61 build 250804 V5.8.61 build 250901

New Features

1. ANPR algorithm updates:
   1) Fix the issue that manual capture of motorcycle license plates reports "unknown".
   2) Optimization for Belgian and Hungarian license plates recognition
   4) Fix issue where ANPR city separator settings do not take effect after restart
   5) Optimization for Georgian license plates recognition

Modify Features

V5.8.61 build 250804:

1. Fix the issue of missing data storage button in the people management mode.
2. Fix the issue of frequent block and allow list downloads causing license plate recognition failure in ANPR cameras
3. Fix the issue of 7xx7 cameras displaying all-black images at night when using IR mode.

V5.8.61 build 250901:

 Fix the issue of the device failing to start due to the frequent reading of EMMC.

Customer Impact and Recommended Action

This update refers to function/compatibility improvement and will take effect automatically after the

Date of Change. We are very sorry for any inconvenience of use-habit changes caused by this action.

For any questions and request for this firmware, please contact our local technical support team.

Hikvision Digital Technology CO., Ltd.

No. 555 Qianmo Road, Binjiang District, Hangzhou
310051, China
Tel: +86-571-8807-5998