Network Video Recorder

Version: V4.84.120_251202

Release Note

Firmware Basic Information	Firmware Version:	V4.84.120_build251202
	SDK Version:	4.0.2509.2
	Play Library:	6.0.0.5
	Web component:	V5.1.46_R0102 build250925
	OpenSDK Version:	V2.16.3

Reason of Upgrade

New features and problem-solving

New Features

1. Channel preview image enlargement requirement
2. Default output volume adjustment, with multiple outputs and consistent volume
3. Solve the problem of hard disk formatting and format the hard disk in parallel
4. The preview screen does not contain HIK information, and the semi-finished package name does not contain DS characters

Modified functions

1. 4 and 8 disk devices, 4, 8, and 16 channel devices reduced from 3G to 2G
2. 4 Disk 32 Channel Non PoE Device DDR Reduced from 16 bits to 8 bits
3. Fix white image issue caused by abnormal termination of image object storage file
4. HTTP guard supports IP and domain names
5. Fix base64 decoding out of bounds issue
6. Fix the issue of incorrect start and end times in some regions during daylight saving time
7. Fix the issue of garbled Arabic text on web and local display
8. Fix defects in RTC time reading and system timing

Customer Impact and Recommended Action

This new firmware upgrade is to improve product performance, and will take effect automatically after upgrading from previous versions. We'd like to inform you the above changes. Also, we are sorry for any possible inconvenience of use-habit changes caused by this action.

For questions or concerns, please contact our local technical support.

Note:
- Hikvision has all rights to alter, modify and cancel this notice.
- Hikvision doesn't give any guarantee for old models' stock.
- Hikvision is not liable for any typing or printing errors.
- For special model's change details, please contact our local technical support team.