Body Worn Camera V2.2.2 Release Notes

Firmware **Basic Information**	Firmware Version:	V2.2.2 build 211116

Reason of Upgrade

Minor bugs fixing;

Bugs Fixed

1. Fix the issue of partial refresh of the UI and the issue of abnormal release of resources
2. Fix the problem that the device is stuck when using NVR for a long time to fetch the stream, log in and log out.

Related product list

Model	DS-MCH508

Customer Impact and Recommended Action

This new firmware upgrade is to improve product performance, and will take effect automatically after upgrading from previous versions. We'd like to inform you the above changes. Also, we are sorry for any possible inconvenience of use-habit changes caused by this action.

For questions or concerns, please contact our local technical support t

Note:

- Hikvision has all rights to alter, modify and cancel this notice.

- Hikvision doesn't give any guarantee for old models' stock.

- Hikvision is not liable for any typing or printing errors.

- For special model's change details, please contact our local technical support team.