

DS-K1T8005 Series Terminal Release Note (2025-02-27)

Device Model: DS-K1T8005EFX DS-K1T8005MFX DS-K1T8005MFWX	Firmware Version	ACS_8005_F2pro_EN_STD_V3.25.0_build241227 ACS_8005_F2pro_EN_N EU_V3.25.0_build241227
DS-K1T8005EFWX DS-K1T8005EFWX-B, DS-K1T8005MFWX-B Naming Rule:	Software	HikCentral AC: https://www.hikvision.com/en/support/download/soft ware/hikcentral-access-control-v2-3-1/ Please add device to HCP with port 80, and port
M for M1 card, E for EM cardB for backup batteryF for Fingerprint, W for Wi-Fi		8000 will not work

Modified Features

- 1. Fixed DST issue
- 2. Solved issue that manually changing attendance status is not working when configured to "auto and manual mode".

DS-K1T8005 Series Terminal Release Note (2024-07-12)

Device Model:		
DS-K1T8005EFX	Firmware	ACS_8005_F2pro_EN_STD_V3.25.0_build240701
DS-K1T8005MFX	Version	ACS_8005_F2pro_EN_N EU_V3.25.0_build240701
DS-K1T8005MFWX		
DS-K1T8005EFWX		
DS-K1T8005EFWX-B,		HikCentral AC:
DS-K1T8005MFWX-B		https://www.hikvision.com/en/support/download/soft
	Software	ware/hikcentral-access-control-v2-3-0/
Naming Rule:		Please add device to HCP with port 80, and port
M for M1 card, E for EM card		8000 will not work
-B for backup battery		



F for Fingerprint, W for Wi-Fi	

Modified Features

- 1. Optimize remote fingerprint collection from Hik-Connect portal.
- 2. Fixed the issue that duplicate "Friday" in attendance report exported from web page.

DS-K1T8005 Series Fingerprint Terminal Release Notes (2024-06-15)

Device Model: DS-K1T8005EFX DS-K1T8005MFX	Firmware Version	ACS_8005_F2pro_EN_STD_V3.25.0_build240419 ACS_8005_F2pro_EN_N EU_V3.25.0_build240419
DS-K1T8005MFWX DS-K1T8005EFWX DS-K1T8005EFWX-B, DS-K1T8005MFWX-B Naming Rule: M for M1 card, E for EM card -B for backup battery F for Fingerprint, W for Wi-Fi	Software	HikCentral AC: https://www.hikvision.com/en/support/download/soft ware/hikcentral-access-control-v2-3-0/ Please add device to HCP with port 80, and port 8000 will not work

Reason of Upgrade

New model DS-K1T8005 series terminals first time released.



New Features



- 1. 2.4-inch LCD screen
- 2. Multiple authentication methods, including fingerprint, M1/EM card (varies from the detail model), and PIN, etc.
- 3. Max. 3000 cards, 3000 fingerprints and 100,000 events
- 4. Supports ISAPI and ISUP 5.0 protocols
- 5. Configuration via the PC web client and mobile web client
- 6. Supports wired network and Wi-Fi (AP mode) (-W only)
- 7. Supports wiring with secure door control unit or card reader via RS-485
- 8. Supports power supply by battery in the bracket (-B only)
- 9. Supports access control and local time and attendance function

Customer Impact and Recommended Action

This update refers to function/compatibility improvement and will take effect automatically after the Date of Change. We are very sorry for any inconvenience of use-habit changes caused by this action. For any questions and request for this firmware, please contact our local technical support team.

Note:

- Hikvision reserves the right to change, alter or withdraw the above notification without prior notice.
- Product design and specifications are subject to change without prior notice.
- The Hikvision firmware may contain errors known as errata, which may cause the product to deviate from published specifications. Current characterized errata are available on request.
- Hikvision is not liable for any typing or printing errors.

Hikvision Digital Technology CO., Ltd.

No. 555 Qianmo Road, Binjiang District, Hangzhou 310051,

China

Tel: +86-571-8807-5998 FAX: +86-571-8993-5635

Email: overseabusiness@hikvision.com