

DS-K1T808 Series Fingerprint Terminal Release Notes (2025-02-27)

Device Model: DS-K1T808MFX, DS-K1T808MFWX DS-K1T808EFX	Firmware Version	ACS_808_F2pro_EN_STD_V3.25.0_build241227 ACS_808_F2pro_EN_NEU_V3.25.0_build241227
DS-K1T808EFWX DS-K1T808EFWX-B, DS-K1T808MFWX-B	Software	HikCentral AC: https://www.hikvision.com/en/support/download/soft-ware/hikcentral-access-control-v2-3-1/
M for M1 card, E for EM card -B for backup battery F for Fingerprint, W for Wi-Fi		Please add device to HCP with port 80, and port 8000 will not work

Modified Features

- 1. Fixed DST issue
- 2. Solved issue that manually changing attendance status is not working when configured to "auto and manual mode".

DS-K1T808 Series Fingerprint Terminal Release Notes (2024-07-12)

Device Model:		
DS-K1T808MFX,	Firmware	ACS_808_F2pro_EN_STD_V3.25.0_build240701
DS-K1T808MFWX	Version	ACS_808_F2pro_EN_NEU_V3.25.0_build240701
DS-K1T808EFX		
DS-K1T808EFWX		
DS-K1T808EFWX-B,		HikCentral AC:
DS-K1T808MFWX-B		https://www.hikvision.com/en/support/download/soft
	Software	ware/hikcentral-access-control-v2-3-0/
Naming Rule:		Please add device to HCP with port 80, and port
M for M1 card, E for EM card		8000 will not work
-B for backup battery		



F for Fingerprint, W for Wi-Fi		

Modified Features

- 1. Optimize remote fingerprint collection from Hik-Connect portal.
- 2. Fixed the issue that duplicate "Friday" in attendance report exported from web page.

DS-K1T808 Series Fingerprint Terminal Release Notes (2024-06-15)

Device Model:		
DS-K1T808MFX,	Firmware	ACS_808_F2pro_EN_STD_V3.25.0_build240419
DS-K1T808MFWX	Version	ACS_808_F2pro_EN_NEU_V3.25.0_build240419
DS-K1T808EFX		
DS-K1T808EFWX		
DS-K1T808EFWX-B,		HikCentral AC:
DS-K1T808MFWX-B		https://www.hikvision.com/en/support/download/soft
	Software	ware/hikcentral-access-control-v2-3-0/
Naming Rule:		Please add device to HCP with port 80, and port
M for M1 card, E for EM card		8000 will not work
-B for backup battery		
F for Fingerprint, W for Wi-Fi		

Reason of Upgrade

New model DS-K1T808 series terminals first time released.





New Features

- 2.4-inch LCD screen
- Multiple authentication methods, including fingerprint (-F only), M1/EM card (varies from the detail model), and PIN, etc.
- Max. 3000 cards, 3000 fingerprints(-F only) and 100,000 events
- Supports ISAPI and ISUP 5.0 protocols
- Configuration via the PC web client and mobile web client
- Supports wired network and Wi-Fi (AP mode) (-W only)
- Supports wiring with secure door control unit or card reader via RS-485
- Supports power supply by battery in the bracket (-B only)
- Supports access control and local time and attendance function

Customer Impact and Recommended Action

This update refers to function/compatibility improvement and will take effect automatically after the Date of Change. We are very sorry for any inconvenience of use-habit changes caused by this action. For any questions and request for this firmware, please contact our local technical support team.

Note:

- Hikvision reserves the right to change, alter or withdraw the above notification without prior notice.
- Product design and specifications are subject to change without prior notice.
- The Hikvision firmware may contain errors known as errata, which may cause the product to deviate from published specifications. Current characterized errata are available on request.
- Hikvision is not liable for any typing or printing errors.



Hikvision Digital Technology CO., Ltd. No. 555 Qianmo Road, Binjiang District, Hangzhou 310051, China

Tel: +86-571-8807-5998 FAX: +86-571-8993-5635 Email: overseabusiness@hikvision.com