

Network Video Recorder

Version: V4.73.109 build 250904

Release Note

	Firmware Version:	V4.73.109_build250904
Firmware Basic Information	SDK Version:	NA
	Play Library:	7.3.8.45
	Web component:	V4.0.1 build 250312
	OpenSDK Version:	V2.12.0 build 220509

Reason of Upgrade

Fix some known issues

New Features

NA

Modified functions

- 1. Fix the issue of failed face library creation
- 2. After upgrading this version, CAN NOT downgrade

Related product list:



	DS-7616NXI-K1(STD)(B)(1x8T)
	D3-7010MAI-K1(31D)(D)(1X01)
	DS-7616NXI-K1(NEU)(B)
	DO 7010NW W1(0TD)(D)
	DS-7616NXI-K1(STD)(B)
	DS-7608NXI-K1/8P(NEU)(B)
	DO 7000NW W1 (ODIOTDID) (Alamate 1
	DS-7608NXI-K1/8P(STD)(B)/Alarm4+1
	DS-7608NXI-K1/8P(STD)(B)
	DC 7600NVI V1(NEU)(D)
	DS-7608NXI-K1(NEU)(B)
EUI NVR	DS-7608NXI-K1(STD)(B)/Alarm4+1
	DS-7608NXI-K1(STD)(B)
	D3-7000NAI-KI(31DJ(D)
	DS-7604NXI-K1/4P(STD)(B)/Alarm4+1
	DS-7604NXI-K1(STD)(B)/Alarm4+1
	D3-7004IVAI-IXI(31D)(D)/ A(d11114+1
	DS-7604NXI-K1/4P(NEU)(B)
	DS-7604NXI-K1/4P(STD)(B)
	טס־/סטקואאו־אבן/ אר (טו ט)(ט)
	DS-7604NXI-K1(NEU)(B)
	DS-7604NXI-K1(STD)(B)
	NO-1004WVI-VT(010)



<u>Customer Impact and Recommended Action</u>

This new firmware upgrade is to improve product performance, and will take effect automatically after upgrading from previous versions. We'd like to inform you the above changes. Also, we are sorry for any possible inconvenience of use-habit changes caused by this action.

For questions or concerns, please contact our local technical support.

Note:

- Hikvision has all rights to alter, modify and cancel this notice.
- Hikvision doesn't give any guarantee for old models' stock.
- Hikvision is not liable for any typing or printing errors.
- For special model's change details, please contact our local technical support team.