

## Network Video Recorder

**Version: V4.32.205\_250811 & V4.32.401\_250811**

### Release Note

|   |                   |  |
|---|-------------------|--|
| <b>Firmware</b><br><b>Basic Information</b> | Firmware Version: | V4.32.205_250811.zip<br>V4.32.401_250811.zip |
|   | SDK Version:      | NA   |
|   | Play Library:     | NA   |
|   | Web component:    | NA   |
|   | OpenSDK Version:  | V2.13.2 build 230829                         |

### Reason of Upgrade

Added new features and problem fixes

### New Features

1. Support IPC resolution level function
2. Support PT33/PT34 privacy masking function

### Modified functions

1. Voice intercom problem repair
2. Fixed the issue of abnormal deletion of the second channel after dual camera IPC connection
3. Resolve the issue of recording at speeds greater than 4x that may jump to the earliest recording in the TF card for playback
4. The maximum supported resolution for a 2-channel device is 500W
5. 2-channel devices do not support adaptive streaming mode

## **Customer Impact and Recommended Action**

This new firmware upgrade is to improve product performance, and will take effect automatically after upgrading from previous versions. We'd like to inform you the above changes. Also, we are sorry for any possible inconvenience of use-habit changes caused by this action.

For questions or concerns, please contact our local technical support.

Note:

- Hikvision has all rights to alter, modify and cancel this notice.
- Hikvision doesn't give any guarantee for old models' stock.
- Hikvision is not liable for any typing or printing errors.
- For special model's change details, please contact our local technical support team.