

Network Camera-V5.7.55_SP3 Release Note (241108)

Firmware Basic Information Firmware version: V5.7.55_SP3_241108

New Features

Modify Function

- 1. Fixed black edge issue in some ZF1 lens cameras.
- 2. Fixed the issue that the Face Capture App does not upload capture alarms and can only be recovered after restarting.

Customer Impact and Recommended Action

This update refers to function/compatibility improvement and will take effect automatically after the Date of Change. We are very sorry for any inconvenience of use-habit changes caused by this action.

For any questions and request for this firmware, please contact our local technical support team.

Remarks:

- Hikvision reserves the right to change, alter or withdraw the above notification without prior notice.
- Product design and specifications are subject to change without prior notice.
- The Hikvision firmware may contain errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.
- Hikvision is not liable for any typing or printing errors.

Hikvision Digital Technology CO., Ltd.

No. 555 Qianmo Road, Binjiang District, Hangzhou 310051,

China

Tel: +86-571-8807-5998

FAX: +86-571-8993-5635

Email: overseabusiness(C)hikvision.com