

## **Network Video Recorder**

Version: V4.63.019\_251203

#### Release Note

	Firmware Version:	V4.63.019_251203
	SDK Version:	V6.1.9.151_build20230203
Firmware	Play Library:	6.0.0.5
Basic Information		7.4.0.0
	Web component:	V4.5.0build240424
	OpenSDK Version:	2.15.3

# Reason of Upgrade

New features and problem-solving

## **New Features**

1. 18 2-disk device kernel supports separate time startup, solving the problem of startup failure caused by high hard disk power during startup

## **Modified functions**

1. Fix security vulnerabilities



## <u>Customer Impact and Recommended Action</u>

This new firmware upgrade is to improve product performance, and will take effect automatically after upgrading from previous versions. We'd like to inform you the above changes. Also, we are sorry for any possible inconvenience of use-habit changes caused by this action.

For questions or concerns, please contact our local technical support.

#### Note:

- Hikvision has all rights to alter, modify and cancel this notice.
- Hikvision doesn't give any guarantee for old models' stock.
- Hikvision is not liable for any typing or printing errors.
- For special model's change details, please contact our local technical support team.