

Network Video Recorder

Version: V4.85.030_build260612

Release Note

Firmware Basic Information	Firmware Version:	V4.85.030_build260612
	SDK Version:	NA
	Play Library:	7.4.2.76
	Web component:	V5.1.45_R0102 build 250918
	OpenSDK Version:	V2.16.3

Reason of Upgrade

New features and problem fixes

New Features

Firmware anti rollback, upgrading to this version cannot downgrade back to the previous version

Modified functions

1. Fixed the issue of device freezing when searching the event search interface and successfully comparing faces by clicking on the last page
2. Fix IPSAN/NAS crash defect
3. Fix the defect of NVR cross network segment IPv6 address not working after manually configuring IPv6 address and saving it.
4. Fixed the issue of upgrade failure caused by querying upgrade packages or obtaining upgrade progress during the upgrade process of fluorite.
5. Fix the issue of UPNP scanning crashing in the security tool
6. Fixed the defect where devices that support wifi dongle only have wifi dongle connected to the network and fluorite is online. After restarting the device, fluorite will not automatically go online.

Customer Impact and Recommended Action

This new firmware upgrade is to improve product performance, and will take effect automatically after upgrading from previous versions. We'd like to inform you the above changes. Also, we are sorry for any possible inconvenience of use-habit changes caused by this action.

For questions or concerns, please contact our local technical support.

Note:

- Hikvision has all rights to alter, modify and cancel this notice.
- Hikvision doesn't give any guarantee for old models' stock.
- Hikvision is not liable for any typing or printing errors.
- For special model's change details, please contact our local technical support team.