

DeepinView Camera V5.9.23 Release Note

Firmware Basic Information	Firmware Version	IPCG_H9H9_V5.9.23_260810
-------------------------------	------------------	--------------------------

■ Modify Features

V5.9.23_260810:

Fix some known bugs.

Customer Impact and Recommended Action

This update refers to function/compatibility improvement and will take effect automatically after the Date of Change. We are very sorry for any inconvenience of use-habit changes caused by this action.

For any questions and request for this firmware, please contact our local technical support team.

Remarks:

- Hikvision reserves the right to change, alter or withdraw the above notification without prior notice.
- Product design and specifications are subject to change without prior notice.
- The Hikvision firmware may contain errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.
- Hikvision is not liable for any typing or printing errors.

Hikvision Digital Technology CO., Ltd.

No. 555 Qianmo Road, Binjiang District, Hangzhou 310051, China

Tel: +86-571-8807-5998

FAX: +86-571-8993-5635

Email: overseabusiness@hikvision.com

Supported Models

[IPCG_H9H9]

Product series	Product Models
IPC 8 Series	iDS-2CD8V446G0/X4-XZHSY(1050/1050)(O-STD)
IPC 8 Series	iDS-2CD8V886G0/X4-XZHSY(1050/1050)(O-STD)
IPC 8 Series	iDS-2CD8V446G0/X4-XZHSY(1050/1050)(O-NEU)
IPC 8 Series	iDS-2CD8V886G0/X4-XZHSY(1050/1050)(O-NEU)