

## IPC

### V 5.5.850 build 220421

## Release Note

<b>Firmware</b>  <b>Basic Information</b>	Firmware Version: V 5.5.850 build 220421
---	---

### Reason of Upgrade

Fixed EMMC issues.

### Related product list

Deepin View	DS-2CD6825G0/C-I(2mm)(O-STD)
	DS-2CD6825G0/C-IS(2mm)(O-NEU)
	DS-2CD6825G0/C-I(2mm)(O-NEU)
	DS-2CD6825G0/C-IS(2mm)(O-STD)

## **Customer Impact and Recommended Action**

This new firmware upgrade is to improve product performance, and will take effect automatically after upgrading from previous versions. We'd like to inform you the above changes. Also, we are sorry for any possible inconvenience of use-habit changes caused by this action.

Note:

- Hikvision has all rights to alter, modify and cancel this notice.
- Hikvision doesn't give any guarantee for old models' stock.
- Hikvision is not liable for any typing or printing errors.
- For special model's change details, please contact our local technical support team.