

PTZ V5.5.821 Release Note (2022-08-16)

| Firmware | | |
|-------------|-------------------|----------------------|
| Basic | Firmware Version: | V5.5.821 Build220712 |
| Information | | |

Features

Modified Features

Fixed some internal bugs

Customer Impact and Recommended Action

This update refers to function/compatibility improvement and will take effect automatically after the Date of Change. We are very sorry for any inconvenience of use-habit changes caused by this action.

For any questions and request for this firmware, please contact our local technical support team.

Remarks:

- Hikvision reserves the right to change, alter or withdraw the above notification without prior notice.
- Product design and specifications are subject to change without prior notice.
- The Hikvision firmware may contain errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.
- Hikvision is not liable for any typing or printing errors.

Hikvision Digital Technology CO., Ltd.

No. 555 Qianmo Road, Binjiang District, Hangzhou 310051,

China

Tel: +86-571-8807-5998 FAX: +86-571-8993-5635

Email: overseabusiness@hikvision.com



| Supported Product List | | |
|------------------------|-----------------------------|--|
| Product Category | Model Number | |
| PT7 | DS-2SE7C144IW-AE(32X/4)(S5) | |
| FIZ | DS-2SE7C124IW-AE(32X/4)(S5) | |