

## IP Camera Firmware Version: V5.7.5

### Release Note

<b>Firmware Basic Information</b>	Firmware Version: IPZEX_H8_EN_STD_5.7.5_221201
---------------------------------------	--

#### 1. New Features

- N/A

#### 2. Improved Features

- Fixed H8 platform-based 8MP device preview stuck
- The capture interval of explosion-proof camera is modified to the minimum 1000ms
- The code stream information superposition of explosion-proof camera is only supported under smart event model, but not under face model
- The audio input volume of the explosion-proof camera can be configured as 0
- Fixed the issue that the EZVIZ APP does not receive the alarm after the device triggers the intrusion alarm
- Fixed the issue of camera return failed when the input volume is set to 0
- Fixed the issue where audio input could not be muted

### Customer Impact and Recommended Action

This update refers to function/compatibility improvement and will take effect automatically after the Date of Change. We are very sorry for any inconvenience of use-habit changes caused by this action. For any questions and request for this firmware, please contact our local technical support team.

#### Remarks:

- Hikvision reserves the right to change, alter or withdraw the above notification without prior notice.
- Product design and specifications are subject to change without prior notice.
- The Hikvision firmware may contain errors known as errata which may cause the product to deviate from published



First Choice for Security Professionals

specifications. Current characterized errata are available on request.

- Hikvision is not liable for any typing or printing errors.

Hikvision Digital Technology CO., Ltd.

No. 555 Qianmo Road, Binjiang District, Hangzhou  
310051, China

Tel: +86-571-8807-5998

		Supported Product List
Product Category	Sub platform	Model Number
IP Camera	IPZEX	DS-2DB4236I-CWX(T5/316L)
IP Camera	IPZEX	DS-2DB4223I-CX(T5/316L)