

# Turbo HD DVR V4.26.011 build 201109 Release Notes

# (2020-11-10)

Firmware Basic Information	Firmware Version:	V4.26.011 build201109
	SDK Version:	V6.1.4.20 build 20200320
	Onvif:	V2.2
	Player:	4.810mini
	Player library:	7.3.8.49
	Web version:	V4.0.1 build 210105
	Client version:	V2.6.13.0 build 20181115

## **Reason of Upgrade**

 Add some new functions, modify some functions, and enhance product quality to meet customers' requirements.

#### **Modified functions**

In order to solve the problems caused by time zone modification: After the device is changed from time zone A to time zone B, the following types of problems will occur when NTP time calibration is turned on (the time calibration source is the PC server).

1. The local time of the device is inconsistent with the time of the PC, and the difference between the device time and the PC time is the absolute value of the time zone

- 2. The email linkage time is the time in time zone A
- 3. RTSP playback positioning time, time zone deviation
- 4. Local backup to CD, file name on CD, time zone deviation

## Available Modes:

K8A5FA	iDS-7204HQHI-M1/FA
K8A5	iDS-7204HQHI-M1/S



First Choice for Security Professionals

-	
K8A4FA	iDS-7204HUHI-M1/FA
	iDS-7204HUHI-M2/FA
	iDS-7208HQHI-M1/FA
	iDS-7208HQHI-M2/FA
K8A4	iDS-7208HQHI-M1/S
	iDS-7208HQHI-M2/S
	iDS-7204HUHI-M1/S
	iDS-7204HUHI-M2/S
K8A3FA	iDS-7208HUHI-M1/FA
	iDS-7208HUHI-M2/FA
	iDS-7216HQHI-M1/FA
	iDS-7216HQHI-M2/FA
K8A3	iDS-7208HUHI-M1/S
	iDS-7208HUHI-M2/S
	iDS-7216HQHI-M1/S
	iDS-7216HQHI-M2/S

### **Customer Impact and Recommended Action**

This new firmware upgrade is to improve product performance, and will take effect automatically after

upgrading from previous versions. We'd like to inform you the above changes. Also, we are sorry for any

possible inconvenience of use-habit changes caused by this action.

For questions or concerns, please contact our local technical support team.

#### Note:

- Hikvision has all rights to alter, modify and cancel this notice.
- Hikvision doesn't give any guarantee for old models' stock.
- Hikvision is not liable for any typing or printing errors.
- For special model's change details, please contact our local technical support team.

Hikvision Digital Technology CO., Ltd. No. 555 Qianmo Road, Binjiang District, Hangzhou 310052, China Tel: +86-571-8807-5998 FAX: +86-571-8993-5635 Email: support@hikvision.com