

Turbo HD DVR V4.71.131 build 230913 Release Notes

Firmware Basic Information	Firmware Version:	V4.71.131 build 230913
	SDK Version:	
	Player library:	7.3.5.0
	Web version:	V4.0.1build230912

Reason of Upgrade

Modify the product design, add new functions and optimize the user experience.

Main update

NA

Available Modes:

300228512	DS-7232HGHI-M2(中性)
300228511	DS-7232HGHI-M2(标配)
300228511	DS-7232HGHI-M2(标配)
300228512	DS-7232HGHI-M2(中性)
300228511	DS-7232HGHI-M2(标配)
300228510	HL-DVR-232G-M2(中性)
300228509	HL-DVR-232G-M2(标配)
300228509	HL-DVR-232G-M2(标配)
300228510	HL-DVR-232G-M2(中性)
300228509	HL-DVR-232G-M2(标配)

Customer Impact and Recommended Action

This new firmware upgrade is to improve product performance, and will take effect automatically after upgrading from previous versions. We'd like to inform you the above changes. Also, we are sorry for any possible inconvenience of use-habit changes caused by this action.

For questions or concerns, please contact our local technical support team.

Note:

- Hikvision has all rights to alter, modify and cancel this notice.
- Hikvision doesn't give any guarantee for old models' stock.
- Hikvision is not liable for any typing or printing errors.
- For special model's change details, please contact our local technical support team.

Hikvision Digital Technology CO., Ltd.
No. 555 Qianmo Road, Binjiang District, Hangzhou 310052,
China
Tel: +86-571-8807-5998
FAX: +86-571-8993-5635
Email: support@hikvision.com