

Body Worn Camera V1.3.1 Release Notes

Firmware Basic Information	Firmware Version: V1.3.10_build200709
---	---------------------------------------

Reason of Upgrade

Minor bugs fixing;

New Features

None

Improved Features

None

Bugs Fixed

1. Fixed the issue of wrong time of recording;

Related product list

Model	DS-MH2311
-------	-----------

Customer Impact and Recommended Action

This new firmware upgrade is to improve product performance, and will take effect automatically after upgrading from previous versions. We'd like to inform you the above changes. Also, we are sorry for any possible inconvenience of use-habit changes caused by this action.

For questions or concerns, please contact our local technical support t

Note:

- Hikvision has all rights to alter, modify and cancel this notice.
- Hikvision doesn't give any guarantee for old models' stock.
- Hikvision is not liable for any typing or printing errors.
- For special model's change details, please contact our local technical support team.