Body Worn Camera Firmware Version: V2.2.1 Release Note

(2021-09-13)

1. Firmware Version Information

Firmware Version	V2.2.1 build 210909
I II II I Walc version	V Z. Z. I Dana Z I O J O J

2. Version Main Updates

2.1 Improved Features

- group intercom function is enhanced, support single call, single call, group call and group invitation, to view the current group members.;
- SDK protocol supports GPS data upload;
- multi-user functionality is optimized to extend from only 40 users to 1000 users, and device local search for when users number than 20;
- EZVIZ upgrade to EZVIZ version 2.0 and supports local CAPTCHA modification
- optimizes the dial module to delay the startup time;
- Support Ehome protocol and the isup protocol simultaneous use;
- Production and other stability optimization;
- Support for link with the HCM, HCP platform;
- IMU Hardware has been removed, software removes electronic anti-shake functionality;
- Series of Large keys and anti-shaking equipment are optimized for image distortion correction(Field of view angle of 121 degrees);
- Add the upgrade version verification, and you cannot upgrade back to the old version after upgrading the new version;
- Equipment upgrade package is distinguished between domestic and overseas versions, domestic equipment can only be upgraded to domestic version, overseas equipment can only be upgraded to overseas version

Supported Product List

Product Category	Model Number
BWC	MCW405
BWC	MCW407
BWC	MCW409
BWC	MCH508

Customer Impact and Recommended Action

This update refers to function/compatibility improvement and will take effect automatically after the Date of Change. We are very sorry for any inconvenience of use-habit changes caused by this action.

For any questions and request for this firmware, please contact our local technical support team.

Remarks:

- Hikvision reserves the right to change, alter or withdraw the above notification without prior notice.
- Product design and specifications are subject to change without prior notice.
- The Hikvision firmware may contain errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.
- Hikvision is not liable for any typing or printing errors.

Hikvision Digital Technology CO., Ltd.

No. 555 Qianmo Road, Binjiang District, Hangzhou 310051, China

Tel: +86-571-8807-5998 FAX: +86-571-8993-5635

Email: overseabusiness@hikvision.com