Body Worn Camera V2.2.2 Release Notes

Firmware	, , .	V0.0.0.044007
Basic Information	Firmware Version:	V2.2.2_211227
Reason of Upg	<u>rade</u>	
Minor bugs fixin	ıg;	
New Features		
None		
Improved Feat	ures	
	<u> </u>	
None		
None		
Bugs Fixed		
1. Fixed the issue of failed format of mass storage card;		

Related product list

Model DS-MCW405

Customer Impact and Recommended Action

This new firmware upgrade is to improve product performance, and will take effect automatically after upgrading from previous versions. We'd like to inform you the above changes. Also, we are sorry for any possible inconvenience of use-habit changes caused by this action.

For questions or concerns, please contact our local technical support t

Note:

- Hikvision has all rights to alter, modify and cancel this notice.
- Hikvision doesn't give any guarantee for old models' stock.
- Hikvision is not liable for any typing or printing errors.
- For special model's change details, please contact our local technical support team.