

Mobile Video Recorder

Version: V5.4.0 Release Note

Firmware Basic Information

DS-MP5604-SD / DS-MP5604

MP5604_EN_GM_5.4.0_220223.zip

DS-MP7608 / DS-MP7608H

MP7608_EN_GM_5.4.0_220212.zip

DS-MP5604N

MP5604N_EN_GM_5.4.0_220212.zip

DS-MP7608HN

MP7608HN_EN_GM_5.4.0_220212.zip

Reason of Upgrade

Add new features and fix minor bug

1.New features

1. Support access to HCP2.2 platform: Support access to HCP2.2 platform, including basic functions such as preview, playback, intercom between platform and MVR, parameter configuration functions, GPS and alarm push functions, passenger flow statistics push functions, Upload driving behavior alarm from AE-VC1B11-ISF camera
2. Support dual network card MVR to configure gateways respectively, take effect according to priority

<div>Local</div> <div>System</div> <div>Network</div> <div>Basic Settings</div> <div>Advanced Settings</div> <div>Video/Audio</div> <div>Image</div> <div>Event</div> <div>Storage</div> <div>Vehicle</div>	TCP/IP	DDNS	Port	3G/4G	Priority	
	Lan	Wlan1				
	Lan Choice	Debug Interface				
	NIC Type	Auto				
	IPv4 Address	10.9.97.217				
	IPv4 Subnet Mask	255.255.255.0				
	IPv4 Default Gateway	10.9.97.254				
	MAC Address	ec:c8:9c:c2:90:ed				
	MTU	1500				
	DNS Server					
Preferred DNS Server	0.0.0.0					
Alternate DNS Server	0.0.0.0					
Network Share						

Local

System

Network

Basic Settings

Advanced Settings

Video/Audio

Image

Event

Storage

Vehicle

TCP/IP

DDNS

Port

3G/4G

Priority

Lan

WLAN1

Lan Choice

Rear Interface

NIC Type

Auto

IPv4 Address

192.168.2.64

IPv4 Subnet Mask

255.255.255.0

IPv4 Default Gateway

192.168.2.1

MAC Address

ec:c8:9c:c2:90:ee

MTU

1500

DNS Server

Preferred DNS Server

0.0.0.0

Alternate DNS Server

0.0.0.0

Network Share

Enable Network Share

Save

Local

System

Network

Basic Settings

Advanced Settings

Video/Audio

Image

Event

Storage

Vehicle

TCP/IP

DDNS

Port

3G/4G

Priority

Enable NetPriority

Cellular

Higher

Wi-Fi

High

Lan0

Middle

Lan1

Save

2.Bug fixes

Fixed the problem that the dial-up status on the web is abnormally displayed, while the actual dial-up is successful

Related product list

56 and 76 series	DS-MP5604N(M12)(O-STD)
	DS-MP5604N(O-STD)
MVR	DS-MP7608HN(M12)(O-STD)
	DS-MP7608HN(O-STD)
	DS-MP7608HN(1T)(O-STD)
	DS-MP7608HN(1T)(M12)(O-STD)
	DS-MP7608HN/GLF/WI58(1T)(EU-STD)
	DS-MP5604N(1T)(O-STD)
	DS-MP7608HN/GW(1T)(O-STD)
	DS-MP7608HN/GW/WI(1T)(O-STD)
	DS-MP7608HN/GW/WI58(1T)(O-STD)
	DS-MP7608HN/GLF/WI58(1T)(M12)(EU-STD)
	DS-MP7608HN/GLF(1T)(EU-STD)
	DS-MP7608HN/GLF/WI(1T)(EU-STD)
	DS-MP7608HN/GLF/WI(1T)(US-STD)
	DS-MP5604N(1T)(M12)(O-STD)
	DS-MP7608HN/GLF/WI58(1T)(M12)(US-STD)
	DS-MP7608HN/GW/WI58(1T)(M12)(O-STD)

	DS-MP5604-SD/GLF(Lite)(EU-STD)
	DS-MP7608(O-STD)
	DS-MP5604(O-STD)
	DS-MP7608H(O-STD)
	DS-MP5604-SD/GLF(US-STD)
	DS-MP5604-SD/GLF/WI58(US-STD)
	DS-MP5604-SD/GLF(EU-STD)
	DS-MP5604-SD/GLF/WI58(EU-STD)
	DS-MP5604-SD(O-STD)
	DS-MP7608H(1T)(O-STD)
	DS-MP7608(1T)(O-STD)
	DS-MP5604(1T)(O-STD)
	DS-MP7608H/GW(O-STD)
	DS-MP7608/GW/WI58(O-STD)
	DS-MP7608/GLF(US-STD)
	DS-MP7608H/GW/WI58(O-STD)
	DS-MP7608/GW(O-STD)
	DS-MP7608H/GLF(EU-STD)
	DS-MP7608/GLF(EU-STD)

Customer Impact and Recommended Action

This new firmware upgrade is to improve product performance, and will take effect automatically after upgrading from previous versions. We'd like to inform you the above

changes. Also, we are sorry for any possible inconvenience of use-habit changes caused by this action.

Note:

- Hikvision has all rights to alter, modify and cancel this notice.
- Hikvision doesn't give any guarantee for old models' stock.
- Hikvision is not liable for any typing or printing errors.
- For special model's change details, please contact our local technical support team.