

Turbo HD DVR V4.30.122 build 201107 Release Note

Firmware	Firmware Version:	V4.30.122 build 201107
Basic	SDK Version:	V6.0.2.5
Information V4.30.220	Onvif Version:	V2.2
	Player:	4.81mini
	Play Library (PlayCtrl.dll)	7.3.5.0
build201107	Web component:	V4.0.1build200628
	IVMS-4200:	2.7.1.51

Reason and Content of Upgrade:

Modify DVR timing mechanism for better user experience.

Customer Impact and Recommended Action

This new firmware upgrade is to improve product performance, and will take effect automatically after upgrading from previous versions. We'd like to inform you the above changes. Also, we are sorry for any possible inconvenience of use-habit changes caused by this action.

For questions or concerns, please contact our local technical support team.

Note:

- Hikvision has all rights to alter, modify and cancel this notice.
- Hikvision doesn't give any guarantee for old models' stock.
- Hikvision is not liable for any typing or printing errors.
- For special model's change details, please contact our local technical support team.

Hikvision Digital Technology CO., Ltd.
No. 555 Qianmo Road, Binjiang District, Hangzhou 310052,

China

Tel: +86-571-8807-5998 FAX: +86-571-8993-5635

Formilia consertabilisticion com 1

