

# **Network Video Recorder**

Version: V4.20.002 build210705

## **Release Note**


(2021-07-29 Internal)

	Firmery and Manadan	V4 20 000 build240705
	Firmware Version	V4.20.002 build210705
	Play Library	7.3.3.0
	Web component	V4.0.1 build 210603
Firmware	Plugin	V3.0.6.46
Basic	ONVIF	V2.2
Information	ISAPI	V2.0
		K51&K52: V2.2.0 build 210623
	Kernel	KY2017: V2.2.0 build 210607
		K72A:V2.2.0 build 210609

### New Feature

### Rebuild All Data in Webpage

This new firmware add a new feature that support repairing database in webpage, you can repair the database remotely now.





### Upgrade Feature

### Upgrade database mechanism

Upgrade database mechanism, optimize recording retrieval speed and stability.

#### Related product list:

Please check the firmware mapping table to check the products this version supports.

#### **Customer Impact and Recommended Action**

This new firmware upgrade is to improve product performance, and will take effect automatically after upgrading from previous versions. We'd like to inform you the above changes. Also, we are sorry for any possible inconvenience of use-habit changes caused by this action.

#### Note:

- Hikvision has all rights to alter, modify and cancel this notice.
- Hikvision doesn't give any guarantee for old models' stock.
- Hikvision is not liable for any typing or printing errors.
- For special model's change details, please contact our local technical support team.