

Turbo HD DVR V4.30.203 build 210616 Release Note

Firmware	Firmware Version:	V4.30.203 Build 210616
Basic	ISUPVersion:	V2.0
Information	Onvif Version:	V2.2
	SDK Version	V7.3.6.81
V4.30.203	OpenSDK:	V2.3.0
build210616	Player:	4.81mini
	Play Library (PlayCtrl.dll)	7.3.5.0
	Web component:	V4.0.1 1build201224

Reason of Upgrade:

• Optimizing Hik-Connect relevant mechanism to improve user experience.

Customer Impact and Recommended Action

This new firmware upgrade is to improve product performance, and will take effect automatically after upgrading from previous versions. We'd like to inform you the above changes. Also, we are sorry for any possible inconvenience of use-habit changes caused by this action.

For questions or concerns, please contact our local technical support team.

Note:

- Hikvision has all rights to alter, modify and cancel this notice.
- Hikvision doesn't give any guarantee for old models' stock.
- Hikvision is not liable for any typing or printing errors.
- For special model's change details, please contact our local technical support team.

Hikvision Digital Technology CO., Ltd. No. 555 Qianmo Road, Binjiang District, Hangzhou 310052, China

Tel: +86-571-8807-5998 FAX: +86-571-8993-5635

