

Turbo HD DVR V4.30.212 build 210618

Release Note

Firmware Basic Information V4.30.212 build210618	Firmware Version:	V4.30.212 build 210618
	ISUPVersion:	V2.0
	Onvif Version:	V2.2
	Player:	4.81mini
	Play Library (PlayCtrl.dll)	7.3.5.0
	Web component:	V4.0.1 1build201224

Reason of Upgrade:

- Optimizing Hik-Connect relevant mechanism to improve user experience.

Customer Impact and Recommended Action

This new firmware upgrade is to improve product performance, and will take effect automatically after upgrading from previous versions. We'd like to inform you the above changes. Also, we are sorry for any possible inconvenience of use-habit changes caused by this action.

For questions or concerns, please contact our local technical support team.

Note:

- Hikvision has all rights to alter, modify and cancel this notice.
- Hikvision doesn't give any guarantee for old models' stock.
- Hikvision is not liable for any typing or printing errors.
- For special model's change details, please contact our local technical support team.

Hikvision Digital Technology CO., Ltd.
No. 555 Qianmo Road, Binjiang District, Hangzhou 310052,
China
Tel: +86-571-8807-5998
FAX: +86-571-8993-5635
Email: sales@hikvision.com