

Network Camera_V5.7.71 Release Note

Firmware Basic Information	Firmware Version	V5.7.71 build 250710
---------------------------------------	------------------	----------------------

New Features

Modified Features

1. Fix RTSP flow defects.
2. Meet the compliance requirements of EU 18031

Customer Impact and Recommended Action

This update refers to function/compatibility improvement and will take effect automatically after the Date of Change. We are very sorry for any inconvenience of use-habit changes caused by this action. For any questions and request for this firmware, please contact our local technical support team.

Remarks:

- Hikvision reserves the right to change, alter or withdraw the above notification without prior notice;
- Product design and specifications are subject to change without prior notice;
- The Hikvision firmware may contain errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request;
- Hikvision is not liable for any typing or printing errors.

Hikvision Digital Technology CO., Ltd.

No. 555 Qianmo Road, Binjiang District, Hangzhou 310051, China

Tel: +86-571-8807-5998

FAX: +86-571-8993-5635

Email: overseabusiness@hikvision.com