

Network Video Recorder

Version: V4.84.110_251011

Release Note

Firmware Basic Information	Firmware Version:	V4.84.110_build251011
	SDK Version:	4.0.2509.2
	Play Library:	6.0.0.5
	Web component:	V5.1.46_R0102 build250807
	OpenSDK Version:	V2.16.3

Reason of Upgrade

New features and problem-solving

New Features

1. This version cannot be downgraded after upgrading
2. After this version, AcuSearch and Auto Synopsis features will be disabled during upgrades to improve upgrade performance, and will be restored after the upgrade is complete
3. Compatible with front-end camera IVS protocol
4. Support 64G eMMC, maintain consistency between 64G eMMC partition and 8G eMMC
5. Supports 8-bit DDR
6. When the input bandwidth is greater than 180M and the output bandwidth is greater than 100M, automatically enable soft interrupt aggregation to cover POE devices and non POE devices.

Modified functions

1. Memory optimization
2. Plugin update to solve the white screen issue in Win11 preview

Customer Impact and Recommended Action

This new firmware upgrade is to improve product performance, and will take effect automatically after upgrading from previous versions. We'd like to inform you the above changes. Also, we are sorry for any possible inconvenience of use-habit changes caused by this action.

For questions or concerns, please contact our local technical support.

Note:

- Hikvision has all rights to alter, modify and cancel this notice.
- Hikvision doesn't give any guarantee for old models' stock.
- Hikvision is not liable for any typing or printing errors.
- For special model's change details, please contact our local technical support team.