

Network Video Recorder

Version: V4.84.031_build251210

Release Note

Firmware Basic Information	Firmware Version:	V4.84.031_build251210
	SDK Version:	4.0.2409.1
	Play Library:	6.0.0.5
	Web component:	V5.0.27_R0102 build 250609
	OpenSDK Version:	V2.16.3

Reason of Upgrade

Fix some known issues.

New Features

NA

Modified functions

1. Fix that devices that support and enable Auto Synopsis will lose 30 seconds of video recording when entering DST.
2. Solve the problem of video loss in extreme network environments.
3. Solve the problem of password reset failure in importing and exporting GUID.

Customer Impact and Recommended Action

This new firmware upgrade is to improve product performance, and will take effect automatically after upgrading from previous versions. We'd like to inform you the above changes. Also, we are sorry for any possible inconvenience of use-habit changes caused by this action.

For questions or concerns, please contact our local technical support.

Note:

- Hikvision has all rights to alter, modify and cancel this notice.
- Hikvision doesn't give any guarantee for old models' stock.
- Hikvision is not liable for any typing or printing errors.
- For special model's change details, please contact our local technical support team.