

Network Camera Firmware Version: V5.8.61 SP Release Note

Firmware Basic Information	Firmware Version:	V5.8.61 build 250804 V5.8.61 build 250901 V5.8.61 build 251217 V5.8.61 build 260327
-----------------------------------	-------------------	--

New Features

V5.8.61 build 250804:

1. ANPR algorithm updates:
 - 1) Fix the issue that manual capture of motorcycle license plates reports "unknown".
 - 2) Optimization for Belgian and Hungarian license plates recognition
 - 4) Fix issue where ANPR city separator settings do not take effect after restart
 - 5) Optimization for Georgian license plates recognition

V5.8.61 build 251217:

1. Newly support AcuSearch on Face Capture mode and Road Traffic mode.

Modify Features

V5.8.61 build 250804:

1. Fix the issue of missing data storage button in the people management mode.
2. Fix the issue of frequent block and allow list downloads causing license plate recognition failure in ANPR cameras
3. Fix the issue of 7xx7 cameras displaying all-black images at night when using IR mode.

V5.8.61 build 250901:

Fix the issue of the device failing to start due to the frequent reading of EMMC.

V5.8.61 build 260327:

Fix some known bugs and improve system stability.

Customer Impact and Recommended Action

This update refers to function/compatibility improvement and will take effect automatically after the Date of Change. We are very sorry for any inconvenience of use-habit changes caused by this action. For any questions and request for this firmware, please contact our local technical support team.

Remarks:

- Hikvision reserves the right to change, alter or withdraw the above notification without prior notice.
- Product design and specifications are subject to change without prior notice.
- The Hikvision firmware may contain errors known as errata which may cause the product to deviate from published specifications.
Current characterized errata are available on request.
- Hikvision is not liable for any typing or printing errors.

Hikvision Digital Technology CO., Ltd.

No. 555 Qianmo Road, Binjiang District, Hangzhou

310051, China

Tel: +86-571-8807-5998