

Network Camera-V5.11.1 Release Note (260826)

Firmware Basic Information	Firmware version:	V5.11.1_260826
----------------------------	-------------------	----------------

New Features

Modify Function

1. Fix the issue of the loss of False Alarm Filtering functionality.
2. Fix the issue in plugin-free playback where, after starting playback, enabling audio, and then dragging the progress bar, an error prompt "Failed to enable audio" appears.

Customer Impact and Recommended Action

This update refers to function/compatibility improvement and will take effect automatically after the Date of Change. We are very sorry for any inconvenience of use-habit changes caused by this action.

For any questions and request for this firmware, please contact our local technical support team.

Remarks:

- Hikvision reserves the right to change, alter or withdraw the above notification without prior notice.
- Product design and specifications are subject to change without prior notice.
- The Hikvision firmware may contain errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.
- Hikvision is not liable for any typing or printing errors.



First Choice for Security Professionals
