

Network Camera-V5.8.40 Release Note

(260821)

Firmware Basic Information	Firmware version:	V5.8.40_260821
----------------------------	-------------------	----------------

New Features

Modify Function

Fix the issue where the bitrate was incorrect after switching between H.264+ and H.265+ in the 2/3 series 6/8MP cameras.

Customer Impact and Recommended Action

This update refers to function/compatibility improvement and will take effect automatically after the Date of Change. We are very sorry for any inconvenience of use-habit changes caused by this action.

For any questions and request for this firmware, please contact our local technical support team.

Remarks:

- Hikvision reserves the right to change, alter or withdraw the above notification without prior notice.
- Product design and specifications are subject to change without prior notice.
- The Hikvision firmware may contain errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.
- Hikvision is not liable for any typing or printing errors.

Hikvision Digital Technology CO., Ltd.
No. 555 Qianmo Road, Binjiang District, Hangzhou 310051,
China
Tel: +86-571-8807-5998
FAX: +86-571-8993-5635
Email: [overseabusiness\(C\)hikvision.com](mailto:overseabusiness(C)hikvision.com)