### **Axiom Hub**

Version: V1.0.8

**Release Note** 

(2021-08-18)

### 1. Firmware Basic Information

Firmware	Firmware Version	V1.0.8_build210809
Basic	Web Version	V4.25.1 build 210629
Information		

#### **Notes:**

- 1. Please update firmware to the latest version to ensure the perfect user experience.
- 2. For installers, it is recommended to install and maintain devices via Hik-ProConnect.

## 2. V1.0.8 Upgrade Note

# **Feature optimization:**

### 1) Cellular Data Usage Optimization

The static cellular of the panel is optimized. After the optimization, the static cellular consumption of the panel within a day is limited to less than 1MB.

#### 2) Battery management function Optimization

### **Remarks:**

- Hikvision reserves the right to change, alter or withdraw the above notification without prior notice.
- Product design and specifications are subject to change without prior notice.
- The Hikvision firmware may contain errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.
- Hikvision is not liable for any typing or printing errors.

Hikvision Digital Technology CO., Ltd. No. 555 Qianmo Road, Binjiang District, Hangzhou 310051, China

Tel: +86-571-8807-5998 FAX: +86-571-8993-5635

Email: overseabusiness@hikvision.com