

DVR V4.21.120 Build 210408

Release Note

Firmware Basic Information V4.21.120 Build 210408	Firmware Version	V4.21.120
	ISAPI Version	V2.0
	ONVIF Version	V2.2
	Player	7.3.5.0
	Play Library (PlayCtrl.dll)	7.3.3.64
	Web component	V4.0.1build210330
	Plug-in version	V3.0.6.46

Reason of Upgrade:

- Improve the performance and stabilization of relevant products, optimize the user experience.

Customer Impact and Recommended Action

This new firmware upgrade is to improve product performance, and will take effect automatically after upgrading from previous versions. We'd like to inform you the above changes. Also, we are sorry for any possible inconvenience of use-habit changes caused by this action.

For questions or concerns, please contact our local technical support team.

Note:

- Hikvision has all rights to alter, modify and cancel this notice.
- Hikvision doesn't give any guarantee for old models' stock.
- Hikvision is not liable for any typing or printing errors.
- For special model's change details, please contact our local technical support team.

Hikvision Digital Technology CO., Ltd.
No. 555 Qianmo Road, Binjiang District, Hangzhou 310052,
China
Tel: +86-571-8807-5998
FAX: +86-571-8993-5635
Email: support@hikvision.com