

# Turbo HD DVR V4.21.103 Build 210910 Release Note

Firmware	Firmware Version:	V4.21.103 build 210910
Basic	SDK Version:	V6.0.2.5
	Onvif Version:	V2.2
Information	Player:	6.0.0.5
V4.21.005	Play Library (PlayCtrl.dll)	7.3.3.64 (K51 K52)
build210910		7.3.5.0(K72A)
	Web component:	V4.0.1

## **Reason of Upgrade:**

• Optimize product performance to improve user experience.

## **New features:**


## 1. 【Hik-Connect reset password function】

Hik-Connect password reset function is supported.

## 2. 【Hik-Connect local unbundling function】


Hik-Connect unbind function is supported in the local interface, and the interface location is as fallows.





#### 3. 【Rebuilding database on webpage】

Support to rebuild database on the Webpage, the interface location is as follows.



#### 4. New features of Hik-ProConnect

The addition of Hik-ProConnect supports operations such as hard disk formatting and device restart.

## **Modified Functions**

#### 1. 【Solve several issues】

- When there is no random code in old version or the random code is ABCDFE,
   Hik-Connect returns a new one to ensure online after upgrading.
- 2) Solve the defects related to Hik-ProConnect IO alarm.



## Released product list:

	DS-7204HGHI-F1 (S)/小威视套装专	DS-7116HGHI-K1 (S)
-HGH	用/L	DS-7108HGHI-F1
	DS-7204HGHI-F1 (S)/小威视专用	DS-7208HGHI-F1/N (S)/小威视套装专
	DS-7208HGHI-F1/N (S)	用/L
	DS-7204HGHI-F1 (S)	N.
	DS-7216HGHI-K1 (S)	DS-7204HGHI-F1 /小威视套装专用/L
	DS-7216HGHI-K2 (S)	DS-7204HGHI-F1/N
	DS-7108HGHI-F1/N	DS-7216HGHI-F2
	DS-7116HGHI-F1/N	DS-7216HGHI-F1
	DS-7104HGHI-F1/N	DS-7104HGHI-F1 /小威视专用
	DS-7104HGHI-F1 (S)/小威视专用	DS-7104HGHI-F1 /小威视套装专用/L
	DS-7108HGHI-F1/N (S)/小威视套装	DS-7208HGHI-F1/N /小威视套装专用/L
	、 <i>,,,</i> ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	DS-7216HGHI-F1/N
	DS-7108HGHI-F1/N (S)	DS-7208HGHI-F1/NB
	DS-7104HGHI-F1 (S)	DS-7204HGHI-F1
	DS-7104HGHI-F1 (S)/小威视套装专	DS-7208HGHI-F1
	用/L	DS-7208HGHI-F2
	DS-7208HGHI-F1/N	
	DS-7204HGHI-F1/N /小威视专用	
	DS-7204HGHI-F1 /小威视专用	
	DS-7116HGHI-F1	
	DS-7104HGHI-F1	
	DS-HiLookI-DVR-208G-F2	DS-Hilookl-DVR-204U-K1 (S)/260
HiLook	DS-HiLookI-DVR-216G-F2	DS-HilookI-DVR-208Q-K2 (S)
IIILOOK	DS-HiLookI-DVR-108G-F1	DS-Hilookl-DVR-216Q-K2 (S)
	DS-HiLookI-DVR-104G-F1	DS-HiLookI-DVR-204G-F1 (S)
	DS-HiLookI-DVR-204G-F1	DS-HiLookI-DVR-116G-K1 (S)
	DS-HiLookI-DVR-116G-F1	DS-HiLookI-DVR-208G-F1 (S)
	DS-HiLookI-DVR-216G-F1	DS-Hilookl-DVR-216U-K2 (S)
	DS-HiLookI-DVR-208G-F1	DS-HiLookI-DVR-216G-K2 (S)
	DS-HiLookI-DVR-108G-F1 (S)	DS-HiLookI-DVR-216G-K1 (S)
	DS-HiLookl-DVR-104G-F1 (S)	DS-HilookI-DVR-204Q-K1 (S)260 小威
	DS-Hilookl-DVR-204Q-K1 (S)/260	± 1T
	DS-Hilookl-DVR-208Q-K1 (S)/260	DS-Hilookl-DVR-224Q-K2
	DS-HilookI-DVR-216Q-K1 (S)/260	DS-HilookI-DVR-232Q-K2
	DS-Hilookl-DVR-208U-K1 (S)/260	
<u>HiWatch</u>	DS-Hiwatchl-HWD-6208MH-G2 (S)	DS-HiwatchI-HWD-6104MH-G2
	DS-Hiwatchl-HWD-7216MH-G2 (S)	(S)/260
	DS-HiwatchI-HWD-6216MH-G2 (S)	DS-HiWatchI-HWD-5104 (S)/ 小威视
	DS-HiWatchI-HWD-5216MH-G2 (S)	/1*1T
	DS-HiWatchI-HWD-5116MH-G2 (S)	DS-HiwatchI-HWD-7108MH-G2
	DS-HiWatchI-HWD-5104 /小威视专	(S)/260



用/1*1T	DS-Hiwatchl-HWD-7104MH-G2
DS-HiWatchI-HWD-5224MH-G2	(S)/260
DS-HiWatchI-HWD-5216MH-G2	DS-HiWatchl-HWD-5116MH-G2
DS-HiWatchI-HWD-5232MH-G2	DS-HiWatchl-HWD-5116H-G2 (S)
DS-HiWatchI-HWD-5104M /小威视	DS-HiWatchI-HWD-5108M (S)
专用/1*1T	DS-HiWatchI-HWD-5104M (S)
DS-HiWatchl-HWD-5108 (S)	DS-HiWatchI-HWD-5116
DS-HiWatchl-HWD-5104 (S)	DS-HiWatchI-HWD-5116M
DS-Hiwatchl-HWD-6108MH-G2	DS-HiWatchI-HWD-5104M (S)小威视
(S)/260	/1*1T
DS-Hiwatchl-HWD-6116MH-G2	DS-HiwatchI-HWD-6104MH-G2 (S)260
(S)/260	套装 1T
	DS-HiWatchI-HWD-6224MH-G2

### Customer Impact and Recommended Action

This new firmware upgrade is to improve product performance, and will take effect automatically after upgrading from previous versions. We'd like to inform you the above changes. Also, we are sorry for any possible inconvenience of use-habit changes caused by this action.

For questions or concerns, please contact our local technical support team.

#### Note:

- Hikvision has all rights to alter, modify and cancel this notice.
- Hikvision doesn't give any guarantee for old models' stock.
- Hikvision is not liable for any typing or printing errors.
- For special model's change details, please contact our local technical support team.

Hikvision Digital Technology CO., Ltd. No. 555 Qianmo Road, Binjiang District, Hangzhou 310052, China

Tel: +86-571-8807-5998 FAX: +86-571-8993-5635