

3.5 inch LED Door Station V2.2.32_221229 Release Note (2023-01-10)

Device Model	DS-KD3003-E6、DS-KD8103-E6、DS-KD8023-E6
Firmware Version	V2.2.32_221229
iVMS-4200 Version	Late version
Hik-Connect APP	Late version

Fix:

- 1、Solve the very small probability of activation failure.

3.5 inch LED Door Station V2.2.32_221212 Release Note (2022-12-20)

Device Model	DS-KD3003-E6、DS-KD8103-E6、DS-KD8023-E6
Firmware Version	V2.2.32_221212
iVMS-4200 Version	Late version
Hik-Connect APP	Late version

Fix:

- 2、Fix known device security vulnerability issues.

3.5 inch LED Door Station V2.2.32_220316 Release Note (2022-03-20)

Device Model	DS-KD3003-E6、DS-KD8103-E6、DS-KD8023-E6
Firmware Version	V2.2.32_220316
iVMS-4200 Version	Late version
Hik-Connect APP	Late version



Fix:

- 3、1. Fixed some bugs.

3.5 inch LED Door Station V2.2.32_220214 Release Note (2022-02-18)

Device Model	DS-KD3003-E6、DS-KD8103-E6、DS-KD8023-E6
Firmware Version	V2.2.32_220214
Ivms-4200 Version	Late version

1. it's a temporary firmware, solved issue, we will release baseline firmware soon
2. when select different language (English in default)from web login interface, cannot login the device, same as below



Customer Impact and Recommended Action

This update refers to function/compatibility improvement and will take effect automatically after the Date of Change. We are very sorry for any inconvenience of use-habit changes caused by this action.

For any questions and request for this firmware, please contact our local technical support team.

Note:

- Hikvision reserves the right to change, alter or withdraw the above notification without prior notice.
- Product design and specifications are subject to change without prior notice.
- The Hikvision firmware may contain errors known as errata, which may cause the product to deviate from published specifications. Current characterized errata are available on request.
- Hikvision is not liable for any typing or printing errors.

Hikvision Digital Technology CO., Ltd.
No. 555 Qianmo Road, Binjiang District, Hangzhou 310051,
China
Tel: +86-571-8807-5998
FAX: +86-571-8993-5635
Email: overseabusiness@hikvision.com