

Value Indoor Station Firmware

V1.4.64 230523 Release Note

(2022-06-14)

| Device Model | DS-KH6220-LE1, DS-KH6320-LE1 |
|-------------------|--------------------------------------|
| Firmware Version | Value Indoor Station: V1.4.64_230523 |
| iVMS-4200 Version | Latest version |

Reason of Upgrade

Fix bugs, enhance products quality and meet customers' requirements.

Modified Features

1. Fixed known security vulnerabilities

For details, please refer:

https://www.hikvision.com/en/support/cybersecurity/security-advisory/security-vulnerability-in-some-hikvision-access-control-intercom/

Value Indoor Station Firmware V1.4.62_220414 Release Note (2022-05-10)

| Device Model | DS-KH6220-LE1, DS-KH6320-LE1 |
|-------------------|--------------------------------------|
| Firmware Version | Value Indoor Station: V1.4.62_220414 |
| iVMS-4200 Version | Latest version |

Optimization

1. Optimized the position of call button on UI display.

Fix Bugs

1. Fixed the sync bug when SADP or SDK modify the network parameters.

Value Indoor Station Firmware



V1.4.56_210119 Release Note (2021-02-01)

| Device Model | DS-KH6220-LE1, DS-KH6320-LE1 |
|-------------------|--------------------------------------|
| Firmware Version | Value Indoor Station: V1.4.56_210119 |
| iVMS-4200 Version | 34.0.10 Build201214 |

New Function

1. Added 12 languages including French, Portuguese (Brazil), Spanish, Russian, Italian, Polish, Czech, Turkish, Vietnamese, Ukrainian, German, and Serbian.

Fix Bugs

1. Fixed the problem of delayed button feedback on KH6220-LE1 device at certain times.