HIKVISION

Incident Detection Camera V4.5.1

Release Note



Legal Information

© 2023 Hangzhou Hikvision Digital Technology Co., Ltd. All rights reserved.

This Document (hereinafter referred to be "the Document") is the property of Hangzhou Hikvision Digital Technology Co., Ltd. or its affiliates (hereinafter referred to as "Hikvision"), and it cannot be reproduced, changed, translated, or distributed, partially or wholly, by any means, without the prior written permission of Hikvision. Unless otherwise expressly stated herein, Hikvision does not make any warranties, guarantees or representations, express or implied, regarding to the Document, any information contained herein.

About this Document

Pictures, charts, images and all other information hereinafter are for description and explanation only. The information contained in the Document is subject to change, without notice, due to updates or other reasons.

Please use this Document with the guidance and assistance of professionals trained in supporting the Product.

LEGAL DISCLAIMER

TO THE MAXIMUM EXTENT PERMITTED BY APPLICABLE LAW, THE DOCUMENT IS PROVIDED "AS IS" AND "WITH ALL FAULTS AND ERRORS". HIKVISION MAKES NO REPRESENTATIONS OR WARRANTIES, EXPRESS OR IMPLIED, INCLUDING BUT NOT LIMITED TO, WARRANTIES OF MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE OR NON-INFRINGEMENT. IN NO EVENT WILL HIKVISION BE LIABLE FOR ANY SPECIAL, CONSEQUENTIAL, INCIDENTAL, OR INDIRECT DAMAGES INCLUDING, AMONG OTHERS, DAMAGES FOR LOSS OF BUSINESS PROFITS, BUSINESS INTERRUPTION, OR LOSS OF DATA, CORRUPTION OF SYSTEMS, OR LOSS OF DOCUMENTATION, WHETHER BASED ON BREACH OF CONTRACT, TORT (INCLUDING NEGLIGENCE), OR OTHERWISE, IN CONNECTION WITH THE USE OF THE DOCUMENT, EVEN IF HIKVISION HAS BEEN ADVISED OF THE POSSIBILITY OF SUCH DAMAGES OR LOSS.

The content of this manual is furnished for informational use only and it is subject to change without notice.

i



TABLE OF CONTENTS

Chapter 1 Firmware Version	1
Chapter 2 New Features	
. Chapter 3 Function Optimization	3
Chapter 4 Issue Repair	
Chapter 5 Related product list	




Chapter 1 Firmware Version

Firmware Version	V4.5.1 220727
------------------	---------------

Chapter 2 New Features


2.1

Support video detection smoke and fire events. Support by all 800W devices.



2.2

Thermal imaging management page is added for iDS-TCS817-C and iDS-TCS817-CR model equipment, which can preview thermal imaging and display the version information of thermal imaging module equipment.





2.3

Support vehicle license plate recognition function.


2.4

Integrate overseas license plate recognition algorithm parameter configuration



2.5

The optional configuration of fan mode is added for tcs800 to control fan startup and shutdown.



2.6

SDK upload adds the field upload of country id and vehicle driving direction.



2.7

Supports add device to platforms milestone, NVR and HCP, and live view, uploading of various vehicle features.

Chapter 3 Function Optimization

Chapter 4 Issue Repair

Chapter 5 Related product list

Incident Detection Camera	iDS-TCS800-C
	iDS-TCS800-CI
	iDS-TCS807-CIR
	iDS-TCS807-CR
	iDS-TCS817-C
	iDS-TCS817-CR

