

Turbo HD DVR V4.20.001 build190430

Release Note

(External)

Firmware Basic Information V4.20.001 build 190430	Firmware Version:	4.20.001 build 190430
	SDK Version:	V5.3.6.35_build20180830
	Player:	4.8mini
	Play Library (PlayCtrl.dll)	7.3.3.61
	Web component:	V4.0.1 build180929
	IVMS-4200:	V2.6.11.4 build20180831

Reason of Upgrade:

Optimize product performance, and no new function updates.

New features:

1. 【Disable Negative Voltage】

Add new button in local GUI to disable Negative Voltage.

2. 【Modify traditional Chinese translation】

Modify traditional Chinese translation, from "藉由 H.265 Pro 供電", to "Powered by H.265 Pro".

3. 【Optimize Heat map function】

- 1) Repair the issue that configuring heat map of analog channel, the function will be failure if rebooting the DVR.
- 2) Repair the issue that adding IP camera to DVR and clicking heat map function, the device will be crashed.

Released product list:

K series DVR	DS-9032HUHI-K8	DS-9024HUHI-K8	DS-8132HUHI-K8
	DS-8124HUHI-K8	DS-7332HUHI-K4	DS-7324HUHI-K4
	DS-9016HUHI-K8	DS-9008HUHI-K8	DS-8132HQHI-K8
	DS-8124HQHI-K8	DS-8116HUHI-K8	DS-8108HUHI-K8
	DS-7332HQHI-K4	DS-7324HQHI-K4	DS-7316HUHI-K4
	DS-7308HUHI-K4	DS-7304HUHI-K4	DS-7208HQHI-K2/P
	DS-7208HQHI-K2	DS-7208HQHI-K1	DS-7204HUHI-K2
	DS-7204HUHI-K1/P	DS-7204HUHI-K1	DS-7204HQHI-K1/P
	DS-7204HQHI-K1	DS-7108HQHI-K1	DS-7104HUHI-K1
	DS-8116HQHI-K8	DS-8108HQHI-K8	DS-7316HQHI-K4
	DS-7308HQHI-K4	DS-7304HQHI-K4	DS-7232HQHI-K2
	DS-7224HQHI-K2	DS-7216HUHI-K2/P	DS-7216HUHI-K2
	DS-7216HQHI-K2/P	DS-7216HQHI-K2	DS-7216HQHI-K1
	DS-7208HUHI-K2/P	DS-7208HUHI-K2	DS-7208HUHI-K1
	DS-7208HTHI-K2	DS-7204HTHI-K2	DS-7204HTHI-K1
	DS-7116HQHI-K1	DS-7108HUHI-K1	DS-7204HQHI-K1/P(B)
	DS-7204HQHI-K1(B)	DS-7104HQHI-K1(B)	

Customer Impact and Recommended Action

This new firmware upgrade is to improve product performance, and will take effect automatically after upgrading from previous versions. We'd like to inform you the above changes. Also, we are sorry for any possible inconvenience of use-habit changes caused by this action.

For questions or concerns, please contact our local technical support team.

Note:

- Hikvision reserves the right to change, alter or withdraw the above notification without prior notice.
- Product design and specifications are subject to change without prior notice.
- The Hikvision firmware may contain errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.
- Hikvision is not liable for any typing or printing errors.

Hikvision Digital Technology CO., Ltd.
No. 555 Qianmo Road, Binjiang District, Hangzhou 310052,
China
Tel: +86-571-8807-5998
FAX: +86-571-8993-5635
Email: support@hikvision.com