

Turbo HD DVR V4.27.000 build 210702 Release Notes (2021-07-03)

| | Firmware Version: | V4.27.000 build 210702 |
|-----------------------------|-------------------|--------------------------|
| Firmware Basic Information | SDK Version: | V6.1.4.20 build 20200320 |
| | Onvif: | V2.2 |
| | Player: | 4.810mini |
| | Player library: | 7.3.8.49 |
| | Web version: | V4.0.1 build210601 |
| | Client version: | V2.6.13.0 build 20181115 |

Reason of Upgrade

 Add some new functions, modify some functions, and enhance product quality to meet customers' requirements.

New features

Released the iDS-7216HUHI-M2/S product with the K92 platform, adding and making the light intelligent HUH-M series (previously only 4,8 channels) completable.

Available Modes:

Customer Impact and Recommended Action

This new firmware upgrade is to improve product performance, and will take effect automatically after upgrading from previous versions. We'd like to inform you the above changes. Also, we are sorry for any possible inconvenience of use-habit changes caused by this action.

For questions or concerns, please contact our local technical support team.

Note:

- Hikvision has all rights to alter, modify and cancel this notice.
- Hikvision doesn't give any guarantee for old models' stock.
- Hikvision is not liable for any typing or printing errors.
- For special model's change details, please contact our local technical support team.



Hikvision Digital Technology CO., Ltd. No. 555 Qianmo Road, Binjiang District, Hangzhou 310052,

China

Tel: +86-571-8807-5998 FAX: +86-571-8993-5635 Email: support@hikvision.com