

---

## Release Notes of Body Worn Camera V2.5.1

<b>Firmware Basic Information</b>	Firmware Version: V2.5.1_build240318
-----------------------------------	--------------------------------------

### Reason of Upgrade

Optimize product performance.

### Notice

Can't downgrade to any previous version after upgrade to V2.5.1.

### Related product list

DS-MCW407(C) Series	DS-MCW407/32G/GLE(C)(O-STD)
---------------------	-----------------------------



First Choice for Security Professionals

DS-MCW407(A) Series	DS-MCW407/32G/GLE(A)(O-STD)
---------------------	-----------------------------

### **Customer Impact and Recommended Action**

This new firmware upgrade is to improve product performance, and will take effect automatically after upgrading from previous versions. We'd like to inform you the above changes. Also, we are sorry for any possible inconvenience of use-habit changes caused by this action.

Note:

- Hikvision has all rights to alter, modify and cancel this notice.
- Hikvision doesn't give any guarantee for old models' stock.
- Hikvision is not liable for any typing or printing errors.
- For special model's change details, please contact our local technical support team.