

DVR 4.20.010 Build210908

Release Note

Firmware	Firmware Version	V4.20.010
Basic	ISAPI Version	V2.0
Information	ONVIF Version	V2.2
	Player	6.0.0.5
V4.20.010	Play Library (PlayCtrl.dll)	7.3.5.0
Build210908	Web component	V4.0.1build210603
	Plug-in version	V3.0.6.46

Reason of Upgrade:

 Upgrade the hardware platform of DS-7208HQHI-K2/P and DS-7204HUHI-K1/P to improve user experience.

<u>Customer Impact and Recommended Action</u>

This new firmware upgrade is to improve product performance, and will take effect automatically after upgrading from previous versions. We'd like to inform you the above changes. Also, we are sorry for any possible inconvenience of use-habit changes caused by this action.

For questions or concerns, please contact our local technical support team.

Note:

- Hikvision has all rights to alter, modify and cancel this notice.
- Hikvision doesn't give any guarantee for old models' stock.
- Hikvision is not liable for any typing or printing errors.
- For special model's change details, please contact our local technical support team.

Hikvision Digital Technology CO., Ltd.

No. 555 Qianmo Road, Binjiang District, Hangzhou 310052,

China

Tel: +86-571-8807-5998 FAX: +86-571-8993-5635 Email: support@hikvision.com